

Summary of ET Leader's Site Environmental Audit in the Reporting Month

Parameters	Date	Observations and Recommendations	Follow-up
Air Quality	NA		
Noise	9 September 2025	Observation:1: The silentup at west site boundary should be enclosed.	The silentup was enclosed.
Water Quality	NA		
Chemical and Construction Waste Management	9 September 2025	Reminder 1: Construction waste and domestic waste should be stored separately.	Covered rubbish bin for domestic waste was provided.
Land Contamination	NA		
Ecological Impact	NA		
Landscape and Visual Impact	9 September 2025	Reminder 1: Two dead branches of T133 are recommended for removal.	Two dead branches of T133 were removed.
	17 September 2025	Reminder 1: The Contractor was reminded to prune the broken part of Tree T142.	Broken part of Tree T142 was removed.
	23 September 2025	Reminder 1: The broken branch should be pruned back to the union. Pruning shall follow "Guild lines on Tree Pruning" of GLTMS, DevB(Dec 2023) "Guild lines on Tree Preservation during Development" GLTMS DevB shall be followed to avoid mechanical injury to trees during construction activities.	Broken part of the tree was removed.
Permit / Licenses	3 September 2025	Reminder 1: NRMM label should be provided for the generator at EBC.	New NRMM label was provided.
Others	NA		