

Summary of ET Leader's Site Environmental Audit in the Reporting Month

Parameters	Date	Observations and Recommendations	Follow-up
Air Quality		NA	
Noise		NA	
Water Quality	12 Oct 2021	Observation 1: Provide mitigation to prevent direct discharge of silt water into the storm drain (Portion 1 – YLSTW).	12 Oct 2021
		Observation 2: Gullies should de-silt near the main entrance of the piling area (Portion 1 – YLSTW).	
		Reminder 1: The Contractor is reminded to provide sandbags along inner edge of U channel to prevent inflow of silty runoff (Portion 1 – YLSTW).	
Chemical and Waste Management		NA	
Land Contamination		NA	
Ecological Impact		NA	
Landscape and Visual Impact	6 Oct 2021	Recommendation 1: Trees behind the dismantling changing room at south boundary should be properly protected according to GLTM of DevB recommended measures or specification for the project (Portion 1 – YLSTW).	6 Oct 2021
	12 Oct 2021	Observation 1: Demolition of changing room ensure removal of concrete debris process do not causing unnecessary damage of branches by backhoe (Portion 1 – YLSTW).	15 Oct 2021
		Observation 2: Re-alignment of water barrier to enlarge Tree Protection Zone (Portion 1 – YLSTW).	
20 Oct 2021	Reminder 1: Demolition works at changing room area should be handled with care to protect trees (Portion 1 – YLSTW).	20 Oct 2021	
Permit / Licenses		NA	
Others		NA	