

## Summary of Observations and Findings in the Reporting Month

Parameters	Date	Observations and Recommendations	Follow-up
Air Quality		NA	
Noise		NA	
Water Quality	5 May 2021	Reminder: The contractor was reminded to properly cover the excavated material and trial trench. (Portion 1 YLSTW)	NA
	20 May 2021	Observation 1: Mitigation measures should be provided to intercept silty runoff from the piling area. (Portion 1 YLSTW)	24 May 2021
	20 May 2021	Observation 2: Enhance mitigation by providing sandbags long inner edge of U channel to prevent inflow of silty runoff. (Portion 1 YLSTW)	24 May 2021
	20 May 2021	Observation 3: Silty deposit on road and in gullies should be cleaned. (Portion 1 YLSTW)	24 May 2021
	25 May 2021	Reminder: Mitigation measures should be provided to prevent runoff from the MIC / temporary administration building area flowing to the open channel outside. (Portion 1 YLSTW)	NA
Chemical and Waste Management		NA	
Land Contamination		NA	
Landscape and Visual Impact	11 May 2021	Reminder: The contractor was reminded to provide protection zones for trees near the workshop / storage areas. (Portion 1 YLSTW)	NA
Permit / Licenses		NA	
Others		NA	