






# Air Quality Monitoring Results



Air Quality Monitoring Results




# Noise Monitoring Results



**Noise Monitoring Results**


# Water Quality Monitoring Results






**Water Quality Monitoring Results**


### Total Suspended Solids at Mid-Flood Tide




### Total Suspended Solids at Mid-Flood Tide




### Total Suspended Solids at Mid-Flood Tide




### Dissolved Oxygen at Mid-Ebb Tide




### Dissolved Oxygen at Mid-Ebb Tide




### Dissolved Oxygen at Mid-Ebb Tide




### Turbidity at Mid-Ebb Tide




### Turbidity at Mid-Ebb Tide




### Turbidity at Mid-Ebb Tide




### Total Suspended Solids at Mid-Ebb Tide



### Total Suspended Solids at Mid-Ebb Tide




### Total Suspended Solids at Mid-Ebb Tide




Ecology Monitoring Results for  
Contract No. SPW 02/2023

Environmental Team for Construction of Yuen long  
Effluent Polishing Plant Stage


Abundance of all avifauna species throughout the monitoring period




Abundance of avifauna species with conservation importance throughout the monitoring period




### Species richness of all avifauna species throughout the monitoring period



### Species richness of avifauna species with conservation importance throughout the monitoring period



Shannon Diversity Index values of all avifauna species throughout the monitoring period



Shannon Diversity Index values of avifauna species with conservation importance throughout the monitoring period

