


# Air Quality Monitoring Results







**Air Quality Monitoring Results** 

## Noise Monitoring Results











**Noise Monitoring Results** 


## Water Quality Monitoring Results




















































Ecology Monitoring Results for Contract No. SPW 02/2023

Environmental Team for Construction of Yuen long Effluent Polishing Plant Stage 1


### Abundance of all avifauna species throughout the monitoring period




#### Abundance of avifauna species with conservation importance throughout the monitoring period




#### Species richness of all avifauna species throughout the monitoring period



#### Species richness of avifauna species with conservation importance throughout the monitoring period



#### Shannon Diversity Index values of all avifauna species throughout the monitoring period



## Shannon Diversity Index values of avifauna species with conservation importance throughout the monitoring period

