

### Summary of ET Leader's Site Environmental Audit in the Reporting Month

Parameters	Date	Observations and Recommendations	Follow-up
Air Quality	7 Nov 2022	Reminder 1: The Contractor is reminded to increase watering for dust suppression during the demolition of sludge digestion tank (Portion 1 - YLSTW).	7 Nov 2022
Noise		NA	
Water Quality		NA	
Chemical and Waste Management	16 Nov 2022	Reminder 1: The Contractor is reminded to provide drip tray for chemical containers to prevent chemical leakage near Tree T188 (Portion 1 - YLSTW).	16 Nov 2022
Land Contamination		NA	
Ecological Impact		NA	
Landscape and Visual Impact	7 Nov 2022	Reminder 1: T184 – T188: Stockpile shall be removed under dripline areas. Proper fence should be provided to indicate Tree Protection Zone (TPZ) (Portion 1 - YLSTW).	7 Nov 2022
	16 Nov 2022	Reminder 1: Removal of stockpile under T188's dripline and erect Tree Protection Zone (TPZ) (Portion 1 - YLSTW).	16 Nov 2022
Permit / Licenses		NA	
Others		NA	